



XYLEM

RESISTOGRAPH

REPORT



DATE: 11/15/2024

LOCATION: DEPOT ST, DAVIDSON, NC

SUBJECT TREE: OAK - DLC TREASURE TREE





1.1


1.3




1.2




1.1



1.2



1.3



OVERVIEW

The Depot St. Oak shows a couple noticeable assessments which are highlighted in 1.1 and 1.3. Measurement 1.1 shows a ~2.5” pocket about 14 inches in to the drill depth. But the graph shows, shortly after, a spike around the center where the heartwood should begin indicating nothing major like a completely hollow center. Measurement 1.3 was taken at the root flare and shows a slight dip for the feed curve at 8.5" depth showing a potential softer wood defect but nothing alarming.

Overall, the oak appears to show signs of healthy interior.